

Model:	9000N
Version:	V1.12
Issue date:	8 th March 2024
Type:	Public

New Features

-

Improvement

- Fix FLAC/ALAC format and Tidal Connect display bugs

Additional information

Firmware update instructions.

1. Turn off the power supply to the device (rear panel mains switch).
2. Unzip the update package, and copy the '9000N' folder to the root of a FAT32 formatted USB drive (maximum 32GB, the folder name must be '9000N' and contents should be one file named 9000N.bin).
3. Insert the USB drive into the 'UPDATE' USB socket on the rear panel of the device.
4. Push and hold the front panel standby button.
5. Turn on the power supply to the device (rear panel mains switch) while continuing to hold the standby button.
6. Release the standby button and the display will show 'MCU firmware programming'. You can ignore any messages prior to this.
7. Allow the device to apply the firmware update. This will take just a few seconds.
8. When the update is complete, the device will go into standby. Switch it back on and it is now ready to use

Change history

V1.11, 15th Jan 2024 (internal release only)

Improvement

- Correct long track time shown

V1.10, 1st Dec 2023

Improvement

- Change long track time format from minutes to XX hours XX minutes

V1.09, 28th Oct 2023

Improvement

- Improve TIDAL and TIDAL connect display effect.

V1.08, 22nd Sep 2023

Improvement

- Supports TuneIn radio stream duration time up to 999 minutes
- Fix a bug whereby occasionally, Russian characters in a track title will cause the 9000N to freeze

V1.07, 1st Sep 2023

Improvement

- Change the language "Deutsche" on the language settings of Menu to "Deutsch".
- Save Mute condition after Standby and On again, but do not save after Power Cycle (Switch on the rear panel)

- Improve the sample rate display for PC USB

V1.04, 14th Aug 2023

Improvement

- Performance improvements for Album artwork and Source Switching.

V1.03

First release version